

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Acura													
Acura	CSX	2008-09	17-20204AK	3	17-30503	28720	20019	1212	2040K	TRW	42753-SNA-A83	35	4
Acura	MDX	2004-06	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Acura	MDX	2007-10	17-20216AK	1	17-30301		20032	1209	1100K	Pacific	42753-STK-A04	35	4
Acura	RDX	2007-10	17-20216AK	1	17-30301		20032	1209	1100K	Pacific	42753-STK-A04	35	4
Acura	RL	2005-08	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Acura	RL	2009-10	17-20204AK	3	17-30502	28981	20019	1211	2040K	TRW	42753-SHJ-A53	35	4
Acura	RL	2009-10	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	Replaces Fixed Angle Sensor	35	4
Acura	TL	2006-08	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Acura	TL(Hi-Line)	2009-10	17-20204AK	3	17-30501		20019	1214	2040K	TRW	42753-TK4-A01	35	4
Acura	TSX	2007-08	17-20216AK	1	17-30301		20032	1209	1100K	Pacific	42753-STK-A04	35	4
Acura	TSX	2009-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42753-TL2-A51	35	4
Acura	ZDX(Hi-Line)	2010	17-20204AK	3	17-30501		20019	1214	2040K	TRW	42753-TK4-A01	35	4
Audi													
Audi	Allroad(315 Mhz)	2001-05	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Audi	A6 Allroad(433 Mhz)	2001-06	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Audi	A6 Allroad(433 Mhz)	2007-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	A6 Allroad(433 Mhz)	2010	17-20211AK	4			20037-40	9011	1090K	Beru	4F0 907 275D	35	4
Audi	A3(315 Mhz)	2006-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Audi	A4(433 Mhz)	2002-08	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	A4 (315 Mhz)	2009-10	17-20202AK	2	17-30401		20017	1053	1030K	Continental	1K0907253D	71	8
Audi	A5(315 Mhz)	2008-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Audi	A6(315 Mhz)	2002-04	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Audi	A6(433 Mhz)	2005-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	A6(433 Mhz)	2010	17-20211AK	4				9011	1090K	Beru	4F0 907 275D	35	4
Audi	A8(315 Mhz)	2001-07	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Audi	A8(433 Mhz)	2000-10	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Audi	Q5(315 Mhz)	2009-10	17-20202AK	2	17-30401		20017	1053	1030K	Continental	1K0907253D	71	8
Audi	Q7(433 Mhz)	2005-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	Q7(433 Mhz)	2010	17-20211AK	4				9011	1090K	Beru	4F0 907 275D	35	4
Audi	R8(433 Mhz)	2008-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	R8(433 Mhz)	2010	17-20211AK	4				9011	1090K	Beru	4F0 907 275D	35	4
Audi	RS4(433 Mhz)	2007-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	RS6(315 Mhz)	2001-05	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Audi	RS6(433 Mhz)	2001-05	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Audi	S4(433 Mhz)	2004-08	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	S5(315 Mhz)	2008-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Audi	S6(433 Mhz)	2004-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Audi	S6(433 Mhz)	2010	17-20211AK	4				9011	1090K	Beru	4F0 907 275D	35	4
Audi	S8(315 Mhz)	2001-07	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Audi	S8(433 Mhz)	2000-10	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Audi	TT(315 Mhz)	2008-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Bentley													
Bentley	Continental GT	2003-05	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Bentley	Continental GT	2006-10	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
BMW													
BMW	1 Series(433 Mhz)	2007-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	3 Series(315 Mhz)	2000-02	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	36 11 8 378 681	35	4
BMW	3 Series(433 Mhz)	2001-06	17-20211AK	4	17-30104		20037-40	9002	1090K	Beru	36 11 8 378 682	35	4
BMW	3 Series(433 Mhz)	2007-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	3 Series(433 Mhz) (September 2009)	2010	17-20211AK	4				9012	1090K	Beru	36 10 6 790 054	35	4
BMW	5 Series(315 Mhz)	2000-02	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	36 11 8 378 681	35	4
BMW	5 Series(433 Mhz)	2002-05	17-20211AK	4	17-30104		20037-40	9002	1090K	Beru	36 11 8 378 682	35	4
BMW	5 Series(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	6 Series(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	7 Series(315 Mhz)	2000-01	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	36 11 8 378 681	35	4

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
BMW	7 Series(433 Mhz)	2002-05	17-20211AK	4	17-30104		20037-40	9002	1090K	Beru	36 11 8 378 682	35	4
BMW	7 Series(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	M Series(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	M Series(433 Mhz) (September 2009)	2010	17-20211AK	4				9012	1090K	Beru	36 10 6 790 054	35	4
BMW	X3(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	X5(433 Mhz)	2001-04	17-20211AK	4	17-30106		20037-40	9003	1090K	Beru	36 14 6 752 128	35	4
BMW	X5(433 Mhz)	2005-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	X6(433 Mhz)	2008-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	Z Series(433 Mhz)	2006-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
BMW	Alpina(433 Mhz)	2004-08	17-20211AK	4	17-30104		20037-40	9002	1090K	Beru	36 11 8 378 682	35	4
Bugatti													
Bugatti	Veyron	2005-06	17-20211AK	4			20037-40	NA	1090K	Beru	NA	NA	
Buick													
Buick	Allure	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Buick	Allure	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Buick	Enclave	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Buick	Enclave	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Buick	LaCrosse	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Buick	LaCrosse	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Buick	Lesabre	2007	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25799331	---	
Buick	Lucerne	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Buick	Ranier(315 Mhz)	2006-07	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Buick	Ranier(315 Mhz)	2007	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25799331	---	
Cadillac													
Cadillac	CTS	2004-07	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Cadillac	CTS	2008-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Cadillac	Deville	2001-05	17-20028AK	3	17-20117	20117	20003	9117	1080K	Schrader	25773946	62	7
Cadillac	DTS	2006	17-20201AK	5	17-20158	20158	20030	1047	1050K	Schrader	15268606	80	9
Cadillac	DTS	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Cadillac	Escalade-ESV-EXT	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
Cadillac	Escalade-ESV-EXT	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
Cadillac	Escalade-ESV-EXT	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
Cadillac	Escalade-ESV-EXT	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
Cadillac	Escalade-ESV-EXT	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Cadillac	Seville	2001-04	17-20028AK	3	17-20117	20117	20003	9117	1080K	Schrader	25773946	62	7
Cadillac	SRX	2004-06	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Cadillac	SRX	2007-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Cadillac	SRX	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Cadillac	STS	2005-08	17-20107AK	4	17-20076	20076	20004	9076	1070K	Schrader	25758220	62	7
Cadillac	STS	2009	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Cadillac	STS	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Cadillac	XLR	2004-09	17-20107AK	4	17-20076	20076	20004	9076	1070K	Schrader	25758220	62	7
Chevrolet													
Chevrolet	Avalanche	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
Chevrolet	Avalanche	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
Chevrolet	Avalanche	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
Chevrolet	Avalanche	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
Chevrolet	Avalanche	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Chevrolet	Aveo	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Chevrolet	Camaro	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Chevrolet	Cobalt	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Chevrolet	Cobalt	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Chevrolet	Colorado	2007-10	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
Chevrolet	Corvette	1997-00	17-20204AK	3	17-28006	28006	20019	8006	2040K	Schrader	10438853	62	7
Chevrolet	Corvette-C5-Z6	2001-04	17-20028AK	3	17-20117	20117	20003	9117	1080K	Schrader	25773946	62	7

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Chevrolet	Corvette-C6	2005-09	17-20107AK	4	17-20076	20076	20004	9076	1070K	Schrader	25758220	62	7
Chevrolet	Corvette	2010	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15268606	80	9
Chevrolet	Equinox	2007-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Chevrolet	Equinox	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	---
Chevrolet	Express Series	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Chevrolet	Express Series	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	G Series	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Chevrolet	HHR	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Chevrolet	HHR	2008-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	HHR	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	---
Chevrolet	Impala	2006-07	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Chevrolet	Impala	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	Malibu(≤ 10/14/07)	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Chevrolet	Malibu	2008-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	---
Chevrolet	Monte Carlo	2006-07	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Chevrolet	Monte Carlo	2007	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25799331	---	---
Chevrolet	Silverado	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
Chevrolet	Silverado	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
Chevrolet	Silverado	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
Chevrolet	Silverado	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
Chevrolet	Silverado	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	SSR	2006-07	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Chevrolet	Suburban	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
Chevrolet	Suburban	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
Chevrolet	Suburban	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
Chevrolet	Suburban	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
Chevrolet	Suburban	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	Tahoe	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
Chevrolet	Tahoe	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
Chevrolet	Tahoe	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
Chevrolet	Tahoe	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
Chevrolet	Tahoe	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
Chevrolet	Trailblazer	2006-09	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Chevrolet	Traverse	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	62	7
Chevrolet	Uplander	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Chevrolet	Volt	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	---
Chrysler													
Chrysler	300	2005-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	68111696AB	71	8
Chrysler	300(433 Mhz)	2007-08	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Chrysler	300(433 Mhz)	2009-10	17-20015AK	2	17-28214	28214	20014	9214	2030K	Schrader	56029400AC	71	8
Chrysler	300(Steel)	2010	17-20018				20018	9398	VS950	Schrader	56029398AA	---	---
Chrysler	300M	2002-04	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	58	6.5
Chrysler	Aspen	2007-09	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Schrader	56029465AB	71	8
Chrysler	Concorde	2002-04	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	58	6.5
Chrysler	Crossfire	2004	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Chrysler	Crossfire	2005	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Schrader	56053030AB	35	4
Chrysler	Crossfire(433 Mhz)	2006-08	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Chrysler	Crossfire	2006-08	17-20201AK	5	17-30405	20066	20030	1051	1050K	Siemens	56053030AB	71	8
Chrysler	Intrepid	2002-04	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	58	6.5
Chrysler	Pacifica	2004	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	71	8

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Chrysler	Pacifica	2004-05	17-20201AK	5	17-30403	20335	20030	1052	1050K	Siemens	04727392AB	71	8
Chrysler	Pacifica	2006-08	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Chrysler	Prowler	2002	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Chrysler	PT Cruiser	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Chrysler	Sebring(433 Mhz)	2007-08	17-20201AK	5	17-30404	28155	20030	1043	1050K	Siemens	68001698AA	71	8
Chrysler	Sebring(315 Mhz)	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Chrysler	Town & Country	2002-03	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Chrysler	Town & Country	2004-05	17-20201AK	5	17-30403	20335	20030	1052	1050K	Siemens	04727392AB	71	8
Chrysler	Town & Country	2006-08	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	56053030AB	71	8
Chrysler	Town & Country (433 Mhz)	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Chrysler	Voyager	2002-03	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Dodge													
Dodge	Avenger	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Dodge	Caliber	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Dodge	Caravan	2002-03	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Dodge	Caravan	2004-05	17-20201AK	5	17-30403	20335	20030	1052	1050K	Siemens	04727392AB	71	8
Dodge	Caravan	2006-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	56053030AB	71	8
Dodge	Challenger (433 Mhz)	2008	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Dodge	Challenger (433 Mhz)	2009-10	17-20015AK	2	17-28214	28214	20014	9214	2030K	Schrader	56029400AC	71	8
Dodge	Charger	2006-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	68001696AB	71	8
Dodge	Charger(433 Mhz)	2008	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Dodge	Charger(433 Mhz)	2009-10	17-20015AK	2	17-28214	28214	20014	9214	2030K	Schrader	56029400AC	71	8
Dodge	Charger(Steel)	2010	17-20018				20018	9398	VS950	Schrader	56029398AA	---	
Dodge	Dakota(HP)	2008-10	17-20015AK	2	17-28154	28154	20013	9154	2030K	Schrader	56029319AB	53	6
Dodge	Durango	2007-09	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Schrader	56029465AB	71	8
Dodge	Grand Caravan	2002-03	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Dodge	Grand Caravan	2004-05	17-20201AK	5	17-30403	20335	20030	1052	1050K	Siemens	04727392AB	71	8
Dodge	Grand Caravan	2006-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051**	1050K or 2030K	Siemens	56053030AB	71	8
Dodge	Grand Caravan (433 Mhz)	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Dodge	Journey(433 Mhz)	2009-10	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Dodge	Magnum	2005-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	68001696AB	71	8
Dodge	Magnum(433 Mhz)	2008	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Siemens	68001698AA	71	8
Dodge	Magnum(433 Mhz)	2009	17-20015AK	2	17-28214	28214	20014	9214	2030K	Schrader	56029400AB	71	8
Dodge	Nitro	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Schrader	56029465AB	71	8
Dodge	Ram(HP-315 Mhz) 1500/2500	2008	17-20015AK	2	17-28154	28154	20013	9154	2030K	Schrader	56029319AB	53	6
Dodge	Ram(433 Mhz) 1500/2500	2009-10	17-20201AK	5	17-30404	28155	20030	1043	1050K	Schrader	56029359AA	71	8
Dodge	Ram(433 Mhz) 1500	2010	17-20018				20018	9398	VS950	Schrader	56029398AA	---	
Dodge	Sprinter	2007-09	17-20198AK	4	17-30406			1042	1098K	Siemens	68038945AA	54	6
Dodge	Stratus	2007	17-20201AK	5	17-30405	20066	20030	1051	1050K	Siemens	56053030AB	71	8
Dodge	Viper	2003-09	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Ferrari													
Ferrari	550	2002-09	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	22 45 49	---	
Ferrari	575	2002-09	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	22 45 49	---	
Ferrari	612	2002-09	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	22 45 49	---	
Ferrari	Enzo	2003-09	17-20211AK	4	17-30108		20037-40	9005	1090K	Beru	22 45 51	---	
Ferrari	FXX	2003-09	17-20211AK	4	17-30108		20037-40	9005	1090K	Beru	22 45 51	---	
Ferrari	Spider	2002-09	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	22 45 49	---	
Ford													
Ford	Escape	2009-10	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Expedition	2003-04		1	17-20096	20096	20002	9096	1060K	Schrader	4L2T1A150BA	44	5
Ford	Expedition	2005-06	17-20096AK	1	17-20135	20135	20002	9135	1060K	Schrader	5L7T1A150AB	44	5
Ford	Explorer	2003-05	17-20096AK	1	17-20096	20096	20002	9096	1060K	Schrader	4L2T1A150BA	44	5
Ford	Freestar	2004-05	17-20096AK	1	17-20135	20135	20002	9135	1060K	Schrader	5L7T1A150AB	44	5
Ford	E Series	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Fiesta	2011	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Focus	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Fusion	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	F 150	2009-10	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	F Series(Heavy Duty)	2009-10	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Mustang	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Super Duty	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford	Transit	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Ford Lincoln Mazda Mercury	Escape-Explorer- Freestar-Mariner- Monteirey- Mountaineer-Tribute	2006	17-21101 17-21102 17-21103	-	17-30010	28385 & 28390	22100/01/02	1048	1194	Siemens & Lear Banded Sensor	6F2Z1A189A-6L2T1A150AA- 6F2A1A176AE-6F2T1A150AE	-	-

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Ford Lincoln Mazda Mercury	B Series-Edge- Escape-Expedition- Explorer-F Series- Freestar-Focus- Mariner-Mark LT- Monterey- Mountaineer-Mustang- Navigator-Ranger- Sport Trac	2007	17-21101 17-21102 17-21103	-	17-30010	28385 & 28390	22100/01/02	1048	1194	Siemens & Lear Banded Sensor	6F2Z1A189A	-	-
Ford Lincoln Mazda Mercury	500-B Series-Crown Victoria-Edge-Escape- Expedition-Explorer-F Series-Focus- Freestyle-Fusion- Grand Marquis- Mariner-Mark LT- Milan-Montego- Mountaineer-Mustang- Navigator-Ranger- Sable-Sport Trac- Taurus-Taurus X- Town Car-Tribute	2008	17-21101 17-21102 17-21103	-	17-30010	28385 & 28390	22100/01/02	1048	1194	Siemens & Lear Banded Sensor	6F2Z1A189A	-	-
Ford Lincoln Mazda Mercury	F Series (Heavy & Super Duty)-E Series- Mark LT (High Pressure)	2007-10	17-21101 17-21102 17-21103	-	17-30011	28395	22100/01/02	1048-HP	1194	Lear Banded Sensor	8C2T1A150BA- 8C2Z1A189A	-	-
Ford/ Lincoln/ Mazda/ Mercury	500-Crown Victoria- Edge-Expedition- Explorer-Flex- Freestyle-Grand Marquis-MKS-Focus- Fusion-Montego- Mustang-MKZ- Navigator-Sable- Taurus-Taurus X- Sport Trac-Ranger- MKX-Milan- Mountaineer-B Series- Town Car	2009	17-21101 17-21102 17-21103	-	17-30010	28385 & 28390	22100/01/02	1048	1194	Siemens & Lear Banded Sensor	6F2Z1A189A- ZC21-37-140 7L1Z-1A189A	-	-
Ford/ Lincoln/ Mazda/ Mercury	Crown Victoria-Edge- Expedition-Explorer- Flex-Grand Marquis- MKS-MKT-MKX- Mountaineer- Navigator-Ranger-	2010	17-21101 17-21102 17-21103	-	17-30010	28385 & 28390	22100/01/02	1048	1194	Siemens & Lear Banded Sensor	7L1Z-1A189A	-	-
GMC													
GMC	Acadia	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
GMC	Acadia	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
GMC	Canyon	2007-10	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
GMC	Envoy	2005-06	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
GMC	Envoy	2007-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
GMC	Savana	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
GMC	Savana	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	---
GMC	Sierra(all)	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
GMC	Sierra(all)	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
GMC	Sierra(all)	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
GMC	Sierra(all)	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
GMC	Sierra(all)	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
GMC	Terrain	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
GMC	Yukon(all)	2004	17-20107AK	4	17-20115	20115	20004	9115	1070K	Schrader	15136883	62	7
GMC	Yukon(all)	2005-06	17-20107AK	4	17-20107	20107	20004	9107	1070K	Schrader	15114379	62	7
GMC	Yukon(all)	2007	17-20015AK	3				NA	2020K	TRW	15825475	62	7
GMC	Yukon(all)	2007	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	TRW Sensor Replacement	80	9
GMC	Yukon(all)	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Honda													
Honda	Accord	2008-10	17-20216AK	1	17-30305		20032	1208	1100K	Pacific	42753-SWA-316	35	4
Honda	Civic	2008-10	17-20204AK	3	17-30503	28720	20019	1212	2040K	TRW	42753-SNA-A83	35	4
Honda	CR-V	2007-10	17-20216AK	1	17-30305		20032	1208	1100K	Pacific	42753-SWA-316	35	4
Honda	Crosstour	2010						NEW		Continental	42753-TP6-A82		
Honda	Element	2006-08	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	42753-SCV-A01	35	4
Honda	Element	2009-10	17-20204AK	3	17-30503	28720	20019	1212	2040K	TRW	42753-SNA-A83	35	4
Honda	Fit	2008	17-20216AK	1	17-30305		20032	1208	1100K	Pacific	42753-SWA-316	35	4
Honda	Fit	2009-10	17-20204AK	3	17-30503	28720	20019	1212	2040K	TRW	42753-SNA-A83	35	4
Honda	Insight	2010	17-20204AK	3	17-30503	28720	20019	1212	2040K	TRW	42753-SNA-A83	35	4
Honda	Odyssey	2006-07	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	42753-SCV-A00	35	4
Honda	Odyssey	2008-10	17-20204AK	3	17-28981	28981	20019	1210	2040K	TRW	42753-SHJ-A82	35	4
Honda	Odyssey	2008-10	17-20206AK	4			20036	1058	2000K	TRW	Replaces Fixed Angle Sensor	35	4
Honda	Odyssey(Touring)	2005-07	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Honda	Odyssey(Touring)	2008-10	17-20204AK	3	17-30502	28981	20019	1211	2040K	TRW	42753-SHJ-A53	35	4
Honda	Odyssey(Touring)	2008-10	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	Replaces Fixed Angle Sensor	35	4
Honda	Pilot(Steel)-2.25"	2005	17-20206AK	4	17-30504	28982	20036	1059	2000K	TRW	42753-S9V-A07	35	4
Honda	Pilot-1.75"	2005-08	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Honda	Pilot	2009-10	17-20216AK	1	17-30301		20032	1209	1100K	Pacific	42753-STK-A04	35	4
Honda	Ridgeline(RT)-2.25"	2006-08	17-20206AK	4	17-30504	28982	20036	1059	2000K	TRW	42753-S9V-A07	35	4
Honda	Ridgeline-1.75"	2006-08	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	42753-S3V-A07	35	4
Honda	Ridgeline(Alloy)	2009-10	17-20204AK	3	17-30502	28981	20019	1211	2040K	TRW	42753-SHJ-A53	35	4
Honda	Ridgeline(Alloy)	2009-10	17-20206AK	4	17-28981	28981	20036	1057	2000K	TRW	Replaces Fixed Angle Sensor	35	4
Honda	S2000	2008-09	17-20216AK	1	17-30303		20032	NA	1100K	Pacific	42753-S2A-315	35	4
Hummer													
Hummer	H2	2008-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Hummer	H3	2006-10	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
Hummer	H3T	2009-10	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
Hyundai													
Hyundai	Accent(Lo-Line)	2008-10	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
Hyundai	Azera	2007-10	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
Hyundai	Elantra	2007-10	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
Hyundai	Elantra(Touring)	2010	17-20201AK	5			20030	NEW	1050K	Continental	52933-2L500		
Hyundai	Entourage	2007-09	17-20206AK	4	17-30201		20037-40	1028	2000K	Lear (Beru design)	52933-4D200	31-40	
Hyundai	Genesis(Hi-Line)	2009-10	17-20204AK	3	17-30507	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
Hyundai	Genesis Coupe	2010						NEW		Continental	52933-2M000		
Hyundai	Santa Fe(Lo-Line)	2007-09	17-20206AK	4	17-30201		20037-40	1028	2000K	Lear (Beru design)	52933-4D200	31-40	
Hyundai	Santa Fe(Hi-Line)	2010	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
Hyundai	Sonata	2007-08	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
Hyundai	Sonata(Lo-Line)	2009-10	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
Hyundai	Tiburon	2007-08	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
Hyundai	Tucson	2006-10	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
Hyundai	Veracruz(Lo-Line)	2007-09	17-20206AK	4	17-30201		20037-40	1028	2000K	Lear (Beru design)	52933-4D200	31-40	
Hyundai	Veracruz(Hi-Line)	2010	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
Infiniti													
Infiniti	EX35	2008	17-20028AK	3	17-30307	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	EX35	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00B	66	7.5
Infiniti	FX35	2003-08	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Infiniti	FX35	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00B	66	7.5
Infiniti	FX45	2003-08	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	FX50	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00B	66	7.5
Infiniti	G35	2003-06	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	G35	2007-08	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00B	66	7.5
Infiniti	G37	2008-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00B	66	7.5
Infiniti	M35	2006-08	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	M35	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	66	7.5
Infiniti	M45	2003-08	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	M45	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	66	7.5
Infiniti	Q45	2003-06	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	QX4	2003	17-20028AK	3	17-20064	20064	20003	9064	1080K	Schrader	40700-CD001	66	7.5
Infiniti	QX56(Steel)	2005-06	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Infiniti	QX56(Alloy)	2004-07	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Infiniti	QX56	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	66	7.5
Infiniti	Ascender	2006-08	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Infiniti	I-290	2007-08	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
Infiniti	I-370	2007-08	17-20217AK	2	17-20131	20131	20031	9131	1110K	Schrader	15122618	62	7
Infiniti	Rodeo	2004	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	35	4
Infiniti	S(315 Mhz)	2008	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	C2Z15017	71	8
Infiniti	S(433 Mhz)	2008	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	C2Z15016	71	8
Infiniti	XF(315 Mhz)	2009-10	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	C2Z15017	71	8
Infiniti	XF(433 Mhz)	2009-10	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	C2Z15016	71	8
Infiniti	XJ(315 Mhz)	2004-10	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	C2Z15017	71	8
Infiniti	XJ(433 Mhz)	2004-10	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	C2Z15016	71	8
Infiniti	XK(315 Mhz)	2005-10	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	C2Z15017	71	8
Infiniti	XK(433 Mhz)	2005-10	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	C2Z15016	71	8
Jeep													
Jeep	Commander	2006-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	56029465AB	71	8
Jeep	Commander (433 Mhz)	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Schrader	56029359AB	71	8
Jeep	Compass	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	68001696AA	71	8
Jeep	Grand Cherokee	2002-04	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	64	7
Jeep	Grand Cherokee	2005-07	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Schrader	68001696AB	71	8
Jeep	Grand Cherokee (433 Mhz)	2008-10	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Schrader	56029359AB	71	8
Jeep	Liberty	2004	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	64	7
Jeep	Liberty	2005-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	56029465AB	71	8
Jeep	Liberty(433 Mhz)	2009	17-20201AK or 17-20013AK	5 or 2	17-30404	28155	20030	1043	1050K or 2030K	Schrader	56029359AB	71	8
Jeep	Patriot	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Siemens	68001696AA	71	8
Jeep	Wrangler(Steel)	2007-10	17-20201AK or 17-20013AK	5 or 2	17-30405	20066	20030	1051 **	1050K or 2030K	Schrader	56029465AB	71	8
Jeep	Wrangler(Steel)	2010	17-20018				20018	9398	VS950	Schrader	56029398AA	71	8

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
The 17-20201AK is to be used on the Siemens sensors and the 17-20013AK is to be used on the Schrader sensors.													
KIA													
KIA	Amanti	2007-09	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
KIA	Amanti(Hi-Line)	2010	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
KIA	Borrego(Lo-Line)	2009-10	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Forte	2010								Continental	52933-2M000		
KIA	Mohave	2009	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Optima(Hi-Line)	2006-10	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
KIA	Rio(Lo-Line)	2007-09	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Rio 5(Lo-Line)	2008-09	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Rondo(Hi-Line)	2006-10	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
KIA	Sedona(Lo-Line)	2006-08	17-20206AK	4	17-30201		20037-40	1028	2000K	Lear (Beru design)	52933-4D200	31-40	
KIA	Sedona(Hi-Line)	2009-10	17-20206AK	4			20036	1068	2000K	Lear (Beru design)	52933-2G200	31-40	
KIA	Sorento	2007-09	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
KIA	Sorento	2011								Continental	52933-2M000		
KIA	Soul	2010								Continental	52933-2M000		
KIA	Spectra-5(Lo-Line)	2006-09	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Sportage	2006-08	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	52933-1FA00	31-40	
KIA	Sportage(Lo-Line)	2009-10	17-20204AK	3	17-30506	28849	20031	1029	2040K	TRW	52933-2F000	31-40	
KIA	Tuscany	2007-08	17-20206AK	4	17-30505	28983	20036	1058	2000K	TRW	Enhanced/Basic	31-40	
Land Rover													
Land Rover	LR2(315 Mhz)	2008-10	17-20201AK	5	17-30409			NEW		Siemens	LR003135	71	8
Land Rover	LR3(433 Mhz)	2002-05	17-20211AK	4	17-30106		20037-40	9003	1090K	Beru	Check VIN	58	6.5
Land Rover	LR3(315 Mhz)	2006-09	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	LR018860	71	8
Land Rover	LR3(433 Mhz)	2006-09	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	LRO18861	71	8
Land Rover	LR4(315 Mhz)	2010						NEW			LR010537	71	8
Land Rover	Range Rover (315 Mhz)	2006-10	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	LR018860	71	8
Land Rover	Range Rover (433 Mhz)	2006-10	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	LRO18861	71	8
Land Rover	Range Rover Sport(315 Mhz)	2006-10	17-20201AK	5	17-30407		20030	1055	1050K	Siemens	LR018860	71	8
Land Rover	Range Rover Sport(433 Mhz)	2006-10	17-20201AK	5	17-30408		20030	1046	1050K	Siemens	LRO18861	71	8
Lexus													
Lexus	ES	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	GS	2005-09	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	GX470	2004-06	17-20217AK	2	17-30317	28345	20031	1205	1110K	Pacific	42607-35010	35	4
Lexus	GX470	2006-09	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	HS Series	2010									42607-75010		
Lexus	IS Series	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	LS	2007-09	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	LX	2005-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	RX	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lexus	SC430	2002-07	17-20221AK	3	17-30308-09-10-11	28310-15-20-25		NA	1120K	Pacific	42607-24040	27	3
Lexus	SC	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Lincoln													
Lincoln	Aviator(433 Mhz)	2003-05	17-20096AK	1	17-20096	20096	20002	9096	1060K	Schrader	4L2T1A150-BA	44	5
Lincoln	Mark LT	2009	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Lincoln	MKZ	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Lincoln	Navigator(433 Mhz)	2003-04	17-20096AK	1	17-20096	20096	20002	9096	1060K	Schrader	4L2T1A150-BA	44	5
Lincoln	Navigator(315 Mhz)	2005-06	17-20096AK	1	17-20135	20135	20002	9135	1060K	Schrader	5L7T1A150-AB	44	5
Mazda													
Mazda	3	2004			17-30410		20030	1056	NA	Siemens	FE01-37-140A/ GN3A-37-140B	71	8
Mazda	3	2005	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	3	2006-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Mazda	5	2006-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	6	2005-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	CX-7	2007-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	CX-9	2007-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	MX-5 Miata	2006-09	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	RX-8	2004			17-30410		20030	1056	NA	Siemens	FE01-37-140A/ GN3A-37-140B	71	8
Mazda	RX-8	2005-10	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	Speed 3	2010	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	Speed 6	2007-08	17-20201AK	5	17-30410		20030	1056	1050K	Siemens	GN3A-37-140B	71	8
Mazda	Tribute	2009-10	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Mercedes-Benz													
Mercedes-Benz	C Class(433 Mhz)	2007-10	17-20015AK	2	17-28214	28214	20014	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	CL Class(315 Mhz)	2000-06	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	CL Class(433 Mhz)	2000-06	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	000 822 3306	35	4
Mercedes-Benz	CL Class (315 Mhz)	2007-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 7917	54	6
Mercedes-Benz	CL Class (433 Mhz)	2007-10	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	CLKClass(315 Mhz)	2006-07	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	CLK Class(433 Mhz)	2007-09	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	CLS Class(315 Mhz)	2006-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 7917	54	6
Mercedes-Benz	CLS Class(433 Mhz)	2006-10	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	E Class(315 Mhz)	2000-05	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	E Class(433 Mhz)	2000-05	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	000 822 33 06	35	4
Mercedes-Benz	E Class(315 Mhz)	2006-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6817	54	6
Mercedes-Benz	E Class(433 Mhz)	2006-10	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	G Class(433 Mhz)	2007-10	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	003 540 0217	53	6
Mercedes-Benz	GLK(433 Mhz)	2010	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	GL Class(315 Mhz)	2007-09	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6617	54	6
Mercedes-Benz	GL Class(433 Mhz)	2007-09	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 6717	54	6
Mercedes-Benz	GL(433 Mhz)	2010	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	M Class(315 Mhz)	2006-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6817	54	6
Mercedes-Benz	M Class(433 Mhz)	2006-10	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	R Class(315 Mhz)	2006-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6817	54	6
Mercedes-Benz	R Class(433 Mhz)	2006-10	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	S Class(315 Mhz)	2000-06	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	S Class(433 Mhz)	2000-06	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	000 822 33 06	35	4
Mercedes-Benz	S Class(315 Mhz)	2007-10	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6817	54	6
Mercedes-Benz	S Class(433 Mhz)	2007-09	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	S(433 Mhz)	2010	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	SL Class(315 Mhz)	2000-05	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	SL Class(433 Mhz)	2000-05	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	000 822 33 06	35	4
Mercedes-Benz	SL Class(315 Mhz)	2006-09	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6817	54	6

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Mercedes-Benz	SL Class(433 Mhz)	2006-09	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 8017	54	6
Mercedes-Benz	SLK Class(433 Mhz)	2007-10	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	004 540 0217	53	6
Mercedes-Benz	SLR Class(315 Mhz)	2004-06	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	000 822 34 06	35	4
Mercedes-Benz	SLR Class(433 Mhz)	2000-06	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	000 822 33 06	35	4
Mercedes-Benz	SLR Class(315 Mhz)	2008-09	17-20203AK	3	17-30411		20037-40	1054	1040K	Siemens	002 540 6617	54	6
Mercedes-Benz	SLR Class(433 Mhz)	2008-09	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	002 540 6717	54	6
Mercury													
Mercury	Mariner	2009-10	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Mercury	Milan	2010	17-20018		17-20315	20315	20018	9315	VS950	Schrader	9L3Z-1A189-A	---	
Mercury	Monterey	2004-05	17-20096AK	1	17-20135	20135	20002	9135	1060K	Schrader	5L7T1A150-AB	44	5
Mercury	Mountaineer	2002-05	17-20096AK	1	17-20096	20096	20002	9096	1060K	Schrader	4L2T1A150-BA	44	5
Mini													
Mini	All(433 Mhz)	2007-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	36 23 6 781 847	35	4
Mini	All(433 Mhz) (September 2009)	2010	17-20211AK	4				9012	1090K	Beru	36 10 6 790 054	35	4
Mitsubishi													
Mitsubishi	Eclipse(Alloy)	2006-10	17-20028AK	3	17-20034	20034	20003	9034	1080K	Schrader	MN103081	45-53	5-6
Mitsubishi	Eclipse(Steel)	2006-07	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	4250A030	45-53	5-6
Mitsubishi	Endeavor(433 Mhz)	2004-06	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	52088990AC	45-53	5-6
Mitsubishi	Endeavor(Sept +)	2006-10	17-20028AK	3	17-20028	20028	20003	9034	1080K	Schrader	MN103081	45-53	5-6
Mitsubishi	Galant(433 Mhz)	2004-06	17-20028AK	3	17-20028	20028	20003	9028	1080K	Schrader	MN103033	45-53	5-6
Mitsubishi	Galant	2007-10	17-20028AK	3	17-20028	20028	20003	9034	1080K	Schrader	MN103081	45-53	5-6
Mitsubishi	Galant(Steel)	2008-09	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	4250A030	45-53	5-6
Mitsubishi	Lancer	2008-09	17-20201AK	5	17-30405	20066	20030	1051	1050K	Siemens	4250A225	45-53	5-6
Mitsubishi	Lancer	2010						NEW		Continental	425B668		
Mitsubishi	Montero	2003-05	17-20028AK	3	17-20034	20034	20003	9034	1080K	Schrader	MN103081	45-53	5-6
Mitsubishi	Outlander	2007-09	17-20201AK	5	17-30405	20066	20030	1051	1050K	Siemens	4250A225	45-53	5-6
Mitsubishi	Raider(HP)	2008-10	17-20015AK	2	17-28154	28154	20013	9154	2030K	Schrader	56029319AB	53	6
Nissan													
Nissan	350Z	2004-06	17-20028AK	3	17-20064	20064	20007	9064	1080K	Schrader	40700-CD001	49	5.5
Nissan	350Z	2007-09	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	71	8
Nissan	370Z(Base)	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JK00C	71	8
Nissan	Altima	2006-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	71	8
Nissan	Armada(Alloy)	2005-08	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Armada(Steel)	2005-06	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Nissan	Armada-LE	2008-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	Cube	2009	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	71	8
Nissan	Cube	2010								Schrader	40700-1AA0C		
Nissan	Frontier	2003-04	17-20028AK	3	17-20064	20064	20007	9064	1080K	Schrader	40700-CD001	36-60	
Nissan	Frontier(Alloy)	2005-08	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Frontier(Steel)	2005-07	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Nissan	Frontier(Steel)	2008-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	GT-R	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	71	8
Nissan	Maxima(Alloy)	2006-07	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Maxima	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	Murano	2003-06	17-20028AK	3	17-20064	20064	20007	9064	1080K	Schrader	40700-CD001	66	7.5
Nissan	Murano	2007-09	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	71	8
Nissan	Murano	2010								Schrader	40700-1AA0C		
Nissan	Pathfinder	2003-04	17-20028AK	3	17-20064	20064	20007	9064	1080K	Schrader	40700-CD001	66	7.5
Nissan	Pathfinder(Steel)	2004	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Nissan	Pathfinder	2005-06	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Pathfinder	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	Quest(Steel)	2004-07	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Nissan	Quest(Alloy)	2005-07	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	78	8.8
Nissan	Quest	2008-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	Rogue	2008-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA01C	68	7.5
Nissan	Sentra(Alloy)	2007-08	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	78	8.8
Nissan	Sentra(Steel)	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	75	8.5
Nissan	Titan(Alloy)	2005-08	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Titan(Steel)	2004-08	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Nissan	Titan(Steel)	2009-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Nissan	Versa	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	71	8
Nissan	Versa(Alloy)	2007-08	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	71	8
Nissan	Xterra	2003-04	17-20028AK	3	17-20164	20064	20007	9064	1080K	Schrader	40700-CD001	66	7.5
Nissan	Xterra	2005-06	17-20028AK	3	17-20161	20161	20007	9161	1080K	Schrader	40700-CK001	49	5.5
Nissan	Xterra(Steel)	2006-07	17-20005AK	1	17-20069	20069	20005	9069	1130K	Schrader	40700-CK002	49	5.5
Nissan	Xterra	2007-10	17-20015AK	2	17-28204	28204	20014	9204	2030K	Schrader	40700-JA02B	49	5.5
Pontiac													
Pontiac	G3	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Pontiac	G5	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Pontiac	G5	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Pontiac	G6(Pre-10/15)	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Pontiac	G6(Post-10/15)	2008-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Pontiac	G8	2008-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Pontiac	Grand Prix	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Pontiac	Montana/SV6	2008	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Pontiac	Solstice	2008-10	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013		
Pontiac	Torrent	2007-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	10394110	80	9
Pontiac	Vibe	2008-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	88974915	35	4
Pontiac	Wave	2008-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Porsche													
Porsche	911(433 Mhz)	2006-08	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	99760602101	31-40	
Porsche	911(433 Mhz)	2009-10	17-20211AK	4	17-30107		20037-40	9008	1090K	Beru	99760602120	31-40	
Porsche	911(315 Mhz)	2006-08	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru		31-40	
Porsche	Boxster(433 Mhz)	2006-10	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	99760602101	31-40	
Porsche	Boxster(315 Mhz)	2006-08	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru		31-40	
Porsche	Carrera GT(433 Mhz)	2004-09	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	99760602101	31-40	
Porsche	Cayenne(433 Mhz)	2002-06	17-20211AK	4	17-30108		20037-40	9005	1090K	Beru	95536166101	31-40	
Porsche	Cayenne(315 Mhz)	2009-10	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	95560602301	31-40	
Porsche	Cayenne(433 Mhz)	2007-09	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	95560602100	31-40	
Porsche	Cayman(433 Mhz)	2006-10	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	99760602101	31-40	
Porsche	Panamera	2010	17-20211AK	4	17-30107		20037-40	9008	1090K	Beru	99760602120	31-40	
Rolls Royce													
Rolls Royce	Phantom(433 Mhz)	2007-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	NA	31-40	
Rolls Royce	Cabrio(433 Mhz)	2007-10	17-20211AK	4	17-30105		20037-40	1027	1090K	Beru	NA	31-40	
Saab													
Saab	9-3(433 Mhz)	2004-07	17-20010AK	2	17-28078	28078	20010	9078	2010K	Schrader	13172567	62	7
Saab	9-3(433 Mhz)	2008-10	17-20010AK	2	17-28078	28078	20010	9078	2010K	Schrader	13227143	62	7
Saab	9-5(433 Mhz)	2004-07	17-20010AK	2	17-28078	28078	20010	9078	2010K	Schrader	13172567	62	7
Saab	9-5(433 Mhz)	2008-10	17-20010AK	2	17-28078	28078	20010	9078	2010K	Schrader	13227143	62	7
Saab	9-7X(315 Mhz)	2005-09	17-20107AK	4	17-20116	20116	20004	9116	1070K	Schrader	25774006	62	7
Saturn													
Saturn	Astra(433 Mhz)	2008-09	17-20010AK	2	17-28078	28078	20010	9078	2010K	Schrader	13172567	62	7
Saturn	Astra	2010	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	12768826	---	
Saturn	Aura(<10/14/07)	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Saturn	Aura(>10/14/07)	2008	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Saturn	Aura	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Saturn	Lamda Crossover	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Schrader	15268606	80	9
Saturn	Outlook	2007-08	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9
Saturn	Outlook	2009-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Saturn	Sky	2008-09	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	15921013	80	9

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Saturn	Vue	2007-10	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	25920615	---	
Scion													
Scion	TC	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Scion	XB	2008-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Scion	XD	2008	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Smart													
Smart	Fortwo(433 Mhz)	2008	17-20203AK	3	17-28214	28214	20016	1049	1040K	Siemens	A0045421518	54	6
Smart	Fortwo(433 Mhz)	2008	17-20015AK	2	17-28214	28214	20016	9214	2030K	Schrader	A0025409017	53	6
Subaru													
Subaru	B9 Tribeca	2006-07	17-20028AK	3	17-20081	20081	20003	9081	1080K	Schrader	28103AG00A	66	7.5
Subaru	Forester	2008-10	17-20008	2	17-28203	28203	20008	9203	VS930	Schrader	28103AG01B	---	
Subaru	Impreza	2008-10	17-20008	2	17-28203	28203	20008	9203	VS930	Schrader	28103AG01B	---	
Subaru	Legacy	2004-07	17-20028AK	3	17-20081	20081	20003	9081	1080K	Schrader	28103AG00A	66	7.5
Subaru	Legacy	2008-10	17-20008	2	17-28203	28203	20008	9203	VS930	Schrader	28103AG01B	---	
Subaru	Outback	2004-07	17-20028AK	3	17-20081	20081	20003	9081	1080K	Schrader	28103AG00A	66	7.5
Subaru	Outback	2008-10	17-20008	2	17-28203	28203	20008	9203	VS930	Schrader	28103AG01B	---	
Subaru	Tribeca	2008-10	17-20008	2	17-28203	28203	20008	9203	VS930	Schrader	28103AG01B	---	
Suzuki													
Suzuki	Equator	2009	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	43130-85Z00	---	
Suzuki	Forenza	2007-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	43130-85Z00	---	
Suzuki	Grand Vitara	2007-10	17-20010AK	2	17-20087	20087	20010	9087	2010K	Schrader	43130-54J20	80	9
Suzuki	Kizashi	2010						NEW			43130-57L00		
Suzuki	Reno	2007-09	17-20008	2	17-20153	20153	20008	9153	VS930	Schrader	43130-85Z00	---	
Suzuki	SX4	2007-10	17-20010AK	2	17-20087	20087	20010	9087	2010K	Schrader	43130-54J20	80	9
Suzuki	Verona	2005-06	17-20010AK	2	17-20087	20087	20010	9082	2010K	Schrader	43130-86Z20	80	9
Suzuki	XL-7	2005-06	17-20010AK	2	17-20087	20087	20010	9087	2010K	Schrader	43130-54J20	80	9
Suzuki	XL-7	2007-10	17-20201AK	5	17-30402	20158	20030	1047	1050K	Siemens	43130-78J00	62	7
Tesla													
Tesla	Roadster	2010									6004985	40-50	
Toyota													
Toyota	4 Runner	2003-05	17-20217AK	2	17-30317	28345	20031	1205	1110K	Pacific	42607-35010	35	4
Toyota	4 Runner	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Toyota	Avalon(USA)	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Avalon(Japan)	2007-08	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Camry(USA)	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Camry(Japan)	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Corolla(USA)	2007-08	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Corolla(Japan)	2007-08	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Corolla(Japan)	2009	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33021	35	4
Toyota	Corolla	2010	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	FJ Cruiser	2008-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Highlander	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Land Cruiser	2005-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Matrix(USA)	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Matrix(Japan)	2007-08	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Toyota	Prius	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	RAV 4	2006-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Sequoia(20 Degrees)	2004-07	17-20217AK	2	17-30316	28365	20031	1204	1110K	Pacific	42607-0C020	35	4
Toyota	Sequoia(40 Degrees)	2004-07	17-20217AK	2	17-30314	28300	20031	1203	1110K	Pacific	42607-0C010	35	4
Toyota	Sequoia(20 Degrees)	2008-10	17-20217AK	2	17-30508	28670	20031	1206	1110K	TRW	42607-0C050	35	4
Toyota	Sequoia(40 Degrees)	2008	17-20217AK	2	17-30508	28670	20031	1206	1110K	TRW	42607-0C060	35	4
Toyota	Sienna(20 Degrees)	2006-10	17-20217AK	2	17-30508	28670	20031	1206	1110K	TRW	42607-0C050	35	4
Toyota	Solara	2006-08	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Tacoma(20 Degrees)	2005-06	17-20217AK	2	17-30316	28365	20031	1204	1110K	Pacific	42607-0C020/AD020	35	4
Toyota	Tacoma(40 Degrees)	2005-06	17-20217AK	2	17-30314	28300	20031	1203	1110K	Pacific	42607-0C010/AD010	35	4
Toyota	Tacoma(40 Degrees)	2007-09	17-20217AK	2	17-30314	28380	20032	1203	1110K	Pacific	42607-04010	35	4
Toyota	Tacoma(20 Degrees)	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Tundra(20 Degrees)	2005	17-20217AK	2	17-30316	28365	20031	1204	1110K	Pacific	42607-0C020	35	4

31 Inc. TPMS Application Chart

Make	Model	Model Year	31 Inc. Parts Kit	31 Inc. Color Indicator	31 Inc. Sensor P/N	Schrader Sensor	Schrader Service Pack	Dill Sensor #	Dill Kit #	Sensor Manufacturer	OE Sensor Part No.	Nut Torque (in-lbs.)	Nut Torque (N.m.)
Toyota	Tundra(40 Degrees)	2005-06	17-20217AK	2	17-30314	28300	20031	1203	1110K	Pacific	42607-0C010	35	4
Toyota	Tundra(20 Degrees)	2006-10	17-20217AK	2	17-30508	28670	20031	1206	1110K	TRW	42607-0C050	35	4
Toyota	Tundra(40 Degrees)	2007-10	17-20217AK	2	17-30508	28670	20031	1206	1110K	TRW	42607-0C060	35	4
Toyota	Venza	2009-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-06011	35	4
Toyota	Yaris	2007-10	17-20216AK	1	17-30316	28365	20032	1204	1100K	Pacific	42607-33011	35	4
Volkswagen													
Volkswagen	Beetle	2008-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	CC	2009-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	EOS	2007-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	GLI	2008-09	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Golf	2010	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	GTI(Standard Hex)	2006-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	GTI(O-ring Hex)	2006-07	17-20207AK	4	17-30413			1041	1031K	Siemens	1K0907253E	71	8
Volkswagen	Jetta(Standard Hex)	2006-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Passat(Standard Hex)	2006-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Passat(O-ring Hex)	2006-08	17-20207AK	4	17-30413			1041	1031K	Siemens	1K0907253E	71	8
Volkswagen	Phaeton(433 Mhz)	2002-04	17-20211AK	4	17-30102		20037-40	9001	1090K	Beru	4D0 907 275C	35	4
Volkswagen	Phaeton(433 Mhz)	2005-07	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Volkswagen	Phaeton(315 Mhz)	2003 -07	17-20211AK	4	17-30102		20037-40	9004	1090K	Beru	4D0 907 275A	35	4
Volkswagen	R32	2008-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Rabbit(Standard Hex)	2006-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Rabbit(O-ring Hex)	2006-07	17-20207AK	4	17-30413			1041	1031K	Siemens	1K0907253E	71	8
Volkswagen	Routan(433 Mhz)	2009-10	17-20201AK	5	17-30404	28155	20030	1043	1050K	Siemens	7B0907253	71	8
Volkswagen	Tiguan	2009-10	17-20202AK	2	17-30401		20017	1053	1030K	Siemens	1K0907253D	71	8
Volkswagen	Touareg(433 Mhz)	2002-06	17-20211AK	4	17-30108		20037-40	9005	1090K	Beru	7L0 907 275B	35	4
Volkswagen	Touareg 2(433 Mhz)	2007-10	17-20211AK	4	17-30103		20037-40	9007	1090K	Beru	4F0 907 275B	35	4
Volvo													
Volvo	C30(433 Mhz)	2007-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	C70(433 Mhz)	2007-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	S40(433 Mhz)	2007-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	S60(315 Mhz)	2004-10	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	30748991	44	5
Volvo	S80(315 Mhz)	2004-07	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	30748991	44	5
Volvo	S80(433 Mhz)	2007-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	V50(433 Mhz)	2008-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	V70(315 Mhz)	2004-07	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	30748991	44	5
Volvo	V70(433 Mhz)	2008-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	31280297	71	8
Volvo	XC60	2009-10	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	31200923	44	5
Volvo	XC70(315 Mhz)	2004-07	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	30748991	44	5
Volvo	XC70(433 Mhz)	2008-10	17-20201AK	5	17-30414		20030	1044	1050K	Siemens	306815550	71	8
Volvo	XC90(315 Mhz)	2005-10	17-20010AK	2	17-20156	20156	20010	9156	2010K	Schrader	31200923	44	5